

Memorandum

Date: September 25, 2025

To: SOUTHERN NEVADA DISTRICT BOARD OF HEALTH

From: Daniel Isler, PE, REHS, Environmental Health Engineer/Supervisor 29

Daniel Burns, PE, REHS, Environmental Health Engineer/Manager D8

Chris Saxton, MPH-EH, REHS, Director of Environmental Health XS on behalf of

Saxton

Cassius Lockett, PhD, District Health Officer

Subject: Variance request for an existing septic system, SNHD Permit #ON0010273, located

at 2625 Barbaradale Cir., Las Vegas, NV 89146 to allow existing trees to encroach

on the septic system

I. BACKGROUND:

Sean Connell, Owner ("Petitioner"), is requesting a variance to obtain approval for a Tenant Improvement in accordance with Section 3 of the *Southern Nevada District Board of Health Regulations Governing Individual Sewage Disposal Systems and Liquid Waste Management* ("SNHD ISDS Regulations") and to allow future building permits to be issued for the property located at Assessor's Parcel Number 163-11-111-004, also known as 2625 Barbaradale Cir., Las Vegas, NV 89146 ("Subject Property").

Petitioner requests a variance from Section 3.7 of the SNHD ISDS Regulations, which states that a "Tenant Improvement approval request shall be denied if the existing individual sewage disposal system (ISDS) is in violation of any of these Regulations." The existing septic system is currently in violation of Section 11.3 of the SNHD ISDS Regulations.

Petitioner further requests a variance from Section 11.3 of the SNHD ISDS Regulations, which states that "trees shall be at least ten feet (10') from both the septic tank and leach field." There are several trees above or near the leach field. Petitioner would like to proceed with their Tenant Improvement approval request and allow the existing trees to remain.

Petitioner states the following with regards to these requirements:

Variance Request for 2625 Barbaradale Cir. September 25, 2025 Page 2 of 18

1. There must be circumstances or conditions which are unique to the applicant, and do not generally affect other persons subject to the regulation:

"This request is based on a nearly forty-year old septic system that is performing as designed in at a private residence to allow for remolding my master bathroom. I am not adding any new fixtures and simply want to re-tile my tub and shower along with adding a new countertop and shower door. The trees in question were planted over twenty years ago and more than ten years before I bought the home. They are the only source of shade in large portion of my property that would be rendered mostly useless half the year if the trees are removed for my family and pets because of the excessive heat."

2. There must be circumstances or conditions which make compliance with the regulation unduly burdensome and cause a hardship to and abridge a substantial property right of the applicant, and the variance is necessary to render substantial justice to and preserve the property rights of the applicant. Please indicate in what manner compliance with the regulation would be burdensome or cause a hardship on your business or how the free use of your property may be affected (if economic factors are an issue, please include estimates regarding the costs that would be incurred by compliance):

"The property is located in an area of Spring Valley not serviced by City Sewers. The nearest main is approximately half a mile from my property at the corner of Sahara and Rainbow. Trenching and installing a new sewer line is cost prohibitive. The bids attached to the prior decision for the home on Starlight show six years ago it was estimated between \$87,000 to \$98,000 to install 475 feet of sewer line. Given the inflation we have all experienced since the pandemic, there is no doubt that cost would be much higher today and likely even doubled.

There is also the effect on my property rights. I'm being told I am not allowed to renovate my bathroom without relandscaping my backyard, and that new landscaping cannot include shade trees for an area of approximately 1700 square feet. That is a significant portion of my lot, even before taking into consideration the land occupied by the house, garage, driveway, and front yard. I bought the house because of size of the backyard which will become mostly useless when it is hot if the only shade is removed. The valley is being encouraged to plant more trees to provide shade, and I have two mature trees not causing any damage to my leach field or tank $I \square m$ being ordered to remove."

3. Granting the variance will not be detrimental or pose a danger to public health and safety. Please provide evidence that the variance request, if approved, will not adversely affect the safe and sanitary operation of the applicant(s) pool, spa, or food establishment:

"The septic tank and leach field are on private property servicing a single family residence. The tank and leach field are currently performing as intended. The number of drain lines and length of each make it highly unlikely the trees in question will do enough damage to cause the system to fail. The trees have been there over twenty years and there has never been a problem with the tank. If the tank or leach field does fail at some point in the future, I will be the only one affected. The risk posed by the variance is a financial one to me and to the health or welfare of the public.

Finally, when purchasing the home we were informed the prior owners did not know they were on septic and thought the pipe in the backyard was a sewer cleanout. They tried draining their pool and flooded the leach field. This is secondhand and I cannot confirm it, but apparently they were

Variance Request for 2625 Barbaradale Cir. September 25, 2025 Page 3 of 18

told they had to remove a large area of turf or fake grass because it was partially covering the leach field and prevented evaporation. It is unclear if the instructions came from the SNHD or SNWA, but presumably it would be SNHD because it involved septic. If that is true, SNHD should have noticed as far back as 2013 or 2014 these trees were present and did not raise the issue prior to me purchasing the home. I would ask that any files or reports related to this home be searched to determine if someone from SNHD visited the home over ten years ago and did not address the trees at that time."

The Subject Property is depicted in Attachment C as Lot 4 of the recorded subdivision known as Hanover Estates, which was approved in 1979. Examination of the Clark County Assessor's records and parcel genealogy show that the Petitioner is the sixth owner of the septic system and obtained the Subject Property in June 2015. An analysis of available aerial photography shows that the trees were planted between Spring 2004 and Fall 2004. The property has not been improved since the adoption of the current regulations in 2009. The existing septic system was approved on April 2, 1986. The existing single-family residence was constructed in 1985.

An analysis of the surrounding area shows that there are 144 permitted septic systems within a square mile of the Subject Property. The Subject Property receives water service from Las Vegas Valley Water District, which receives water from the Colorado River. The nearest sewer connection point is approximately 840 feet from the Subject Property.

II. RECOMMENDATION:

The existing trees located on and near the head of the leach field pose a risk to the septic system via root intrusion. Root intrusion can cause hydraulic failure, which may result in sewage backup into the structures being serviced by the septic system or surfacing of sewage over the leach field; however, the presence of trees allows for uptake of the effluent by the roots, which may improve treatment of the effluent.

Staff are of the opinion that granting the variance would not endanger public health or safety; however, staff recommend DENIAL of the variance due to the Subject Property's use of Colorado River Water, the location of the trees directly above and near the head of the leach field, and the system's age. If the Board of Health approves the variance, staff recommend approval with the following conditions outlined in Section III.

III. CONDITIONS:

If approved, staff recommend the following conditions:

1. Petitioners and their successor(s) in interest shall abide by all local governmental regulations requiring connection to community sewage systems. Use of the ISDS shall be discontinued and the structure it serves shall be connected to any community sewage system constructed in the future to within four hundred (400) feet of the applicant's property line when connection can be made by gravity flow and the owner(s) are notified and legally required to do so.

Variance Request for 2625 Barbaradale Cir. September 25, 2025 Page 4 of 18

- 2. Petitioners and their successor(s) will abide by the operation and maintenance requirements of the most current SNHD Regulations governing individual sewage disposal systems.
- 3. No additional trees are allowed within ten feet (10') of the existing septic system.
- 4. The variance will be in effect until the existing residential septic system is inactivated, removed, or if the property changes land use. Conversion of the existing septic system for commercial use will result in the variance becoming null and void.
- 5. Petitioners and their successor(s) must provide a copy of the variance to potential buyers as part of the disclosure process per NRS 113.

Attachments:

- A. Variance Candidate Application
- B. Justification Letter from the Petitioner
- C. Hanover Estates Subdivision Map
- D. Tenant Improvement Review by SNHD Staff (SR0056341)
- E. Final Inspection Report and Plot Plan for ON0010273
- F. Septic Tank Inspection by Master Jetting Sewer Specialist LLC
- G. Public Notice

Attachment A: Variance Candidate Application (Page 1 of 2)

I am requesting a variance based on this board's criteria as follows:

There must be circumstances or conditions which are unique to the petitioner;

This request is based on a nearly forty-year old septic system that is performing as designed in at a private residence to allow for remolding my master bathroom. I am not adding any new fixtures and simply want to re-tile my tub and shower along with adding a new countertop and shower door. The trees in question were planted over twenty years ago and more than ten years before I bought the home. They are the only source of shade in large portion of my property that would be rendered mostly useless half the year if the trees are removed for my family and pets because of the excessive heat.

2. Compliance is unduly burdensome and affects my property rights;

The property is located in an area of Spring Valley not serviced by City Sewers. The nearest main is approximately half a mile from my property at the corner of Sahara and Rainbow. Trenching and installing a new sewer line is cost prohibitive. The bids attached to the prior decision for the home on Starlight show six years ago it was estimated between \$87,000 to \$98,000 to install 475 feet of sewer line. Given the inflation we have all experienced since the pandemic, there is no doubt that cost would be much higher today and likely even doubled.

There is also the effect on my property rights. I'm being told I am not allowed to renovate my bathroom without relandscaping my backyard, and that new landscaping cannot include shade trees for an area of approximately 1700 square feet. That is a significant portion of my lot, even before taking into consideration the land occupied by the house, garage, driveway, and front yard. I bought the house because of size of the backyard which will become mostly useless when it is hot if the only shade is removed. The valley is being encouraged to plant more trees to provide shade, and I have two mature trees not causing any damage to my leach field or tank I'm being ordered to remove.

Granting a variance will not pose a risk to the public.

The septic tank and leach field are on private property servicing a single family residence. The tank and leach field are currently performing as intended. The number of drain lines and length of each make it highly unlikely the trees in question will do enough damage to cause the system to fail. The trees have been there over twenty years and there has never been a problem with the tank. If the tank or leach field does fail at some point in the future, I will be the only one affected. The risk posed by the variance is a financial one to me and to the health or welfare of the public.

Finally, when purchasing the home we were informed the prior owners did not know they were on septic and thought the pipe in the backyard was a sewer cleanout. They tried draining their pool and flooded

Variance Request for 2625 Barbaradale Cir. September 25, 2025 Page 6 of 18

Attachment A: Variance Candidate Application (Page 2 of 2)

the leach field. This is secondhand and I cannot confirm it, but apparently they were told they had to remove a large area of turf or fake grass because it was partially covering the leach field and prevented evaporation. It is unclear if the instructions came from the SNHD or SNWA, but presumably it would be SNHD because it involved septic. If that is true, SNHD should have had notice as far back as 2013 or 2014 these trees were present and did not raise the issue prior to me purchasing the home. I would ask that any files or reports related to this home be searched to determine if someone from SNHD visited the home over ten years ago and did not address the trees at that time.

Sincerely,

Sean P. Connell

Attachment B: Justification Letter from Petitioner (Page 1 of 2)

June 20, 2025

VIA U.S. MAIL

To: Southern Nevada Health District 280 S. Decatur Blvd. Las Vegas, NV. 89107

From:

Sean Connell 2625 Barbaradale Cir. Las Vegas, NV 89146

Re: Parcel # 163-11-111-004

To whom this may concern:

I hereby make application and petition the Southern Nevada District Board of Health for a variance to the Regulations Governing Individual Sewage Disposal and Liquid Waste Management Section 11.3 stating "All trees shall be at least ten feet (10') from both the septic tank and leach field."

This variance request is made to permit renovation of an existing bathroom to include replacement of an existing bathtub, replacement of two existing sinks and fixtures, tiling of the shower and tub surround, and installation of a new steam shower unit. As stated in conditional approval for Permit Number BD25-18796, the total number of fixtures for the property is not changing. However, the approval has been conditioned upon the removal of two or three mature trees. In support of this request are the following attached exhibits:

- The report of Master Jetting Sewer Specialist LLC Licensed #NV20212142881 regarding the condition and functioning of the septic system and perceived impact of the trees in question;
- This boards prior approval of a similar variance for a home at 6075 Starlight Dr, Las Vegas, NV wherein you stated, "the presence of trees allows for uptake of the effluent by the roots, which may improve treatment of the effluent."
- An email from June 6, 2025, wherein the SNHD environmental health engineer opines the trees
 in question have been present for at least 21 years along with an aerial photograph of the area
 in question.
- A second email from the same engineer dated June 9, 2025, detailing the extensive work required to remove the trees including potentially introducing new chemicals to the soil to kill the roots.
- A photograph and drawing provided when I purchased the home in 2015 showing the tank installation in 1986 and area of the leach field with six drain lines at least fifty feet in length.
- 6. A photograph from the ground level of the area in question.

7915 West Sahara Ave. Suite 104 Las Vegas, NV 89117 PHONE FAX EMAIL

NE 702.330.4505 702.825.0141 IL sean@mlolegal.com

Attachment B: Justification Letter from Petitioner (Page 2 of 2)

A screen shot from https://mavorsfundlv.org/tree-initiative/ showing the City's current program trying to raise money to plant 60,000 new trees in the next 25 years.

The legal description of said property is APN # 163-11-111-004, further described as

2625 Barbaradale Cir., Las Vegas, NV 89146.

I have owned the property since June 2015.

Attachment C: Hanover Estates Subdivision Map

HANOVER ESTATES SAHARA AVE. THE E1/2, SE1/4, NW1/4, NW1/4, SECTION 11, T.21 S., R.60 E., M.D.M. CLARK COUNTY, NEVADA NORTH SCALE: 1":50" SURVEYOR'S CERTIFICATE UNDEVELOPED 5.85°24'44" E. ~ 353.76" THIS IS A TRUE AND ACCURATE REPRESENTATION OF THE LANDS SURVEYED UNDER MY SUPERVISION AT THE INSTANCE OF M.S. SERVICE COMPORATION. LAREDO AVE. 2. THE LANDS SURVEYED LIE WITHIN A PORTION OF THE E1. SE1. NW1, NW1, SECTION 11. T215. RECE, M.D.H., AND THE SURVEY WAS COMPLETED ON JUNE 14.1979. 3. THIS PLAT COMPLIES WITH THE APPLICABLE STATE STATUTES AND ANY LOCAL ORDINANCES. THE MONUMENTS WILL BE OF THE CHARACTER SHOWN AND OCCUPY THE POSITIONS IN-DICATED BY I AUG 1983, AND THAT AN APPROPRIATE PERFORMANCE BOND HAS BEEN POSTED WITH THE GOVERNING BODY TO ASSURE THER INSTALLATION. June 19, 1972 LEGAL DESCRIPTION BEING THE E) OF THE SEL OF THE MAL OF THE NAL OF SECTION 11, T215, R60E, M.D.M., CLARK COUNTY, NEWADA, CONTAINING 5,1083 ACRES. UNDEVELOPED **APPROVALS** PRIVATE STREET NO. 10 IS LAUDERHILL & AVE ATTEST! South Buman Certuro Cambino N 8 17 21 W - 151 75' 10 REDWOOD RAINBOW BLVD. ELDORA ST.

CURVE DATA

DEVELOPED

Attachment D: Tenant Improvement Review by SNHD Staff (SR0056341) (Page 1 of 4)

SOUTHERN NEVADA HEALTH DISTRICT 280 SOUTH DECATUR BLVD • PO BOX 3902 • LAS VEGAS, NV • 89127 • 702-759-0660 (DIRECT)• 702-759-1000(24 HOURS)

REPORT AND/OR NOTICE OF INSPECTION

EHS 2177	PERMIT NUMBER ON0010273	FACILITY CONNELL CAROL J & SEAN P				ADDRESS 2625 Barbaradale CIR Las Vegas, NV 89146-5160					
DIST 36	CITY Las Vegas	APN# 163-11-	111	-004			SR # SR0056341			ATER SOUR ublic Water S	
CURRENT ACTION 628	Service Date 06/04/2025	Status 92		Time In 13:00	Time 14:0		Result 83				
020	Travel Minutes	Miles	Vi	olations Alle	eged	Violatio	ons Actual	Future Actio	n	Action	Date

NOTIFIED OF THE FOLLOWING

The tenant improvement for the bathroom remodel is CONDITIONALLY APPROVED.

The total number of fixtures on the property is not changing. The house will have a total of 21 fixtures. The septic tank capacity of 1500 gallons can accommodate a maximum of 35 fixture units.

However, compliance issues have been observed and conditions have been placed. If these conditions are met, the tenant improvement may be re-evaluated for re-approval.

 There are a few trees on and within 10ft of the leach field and septic tank. As stated in Section 11.3 of the Individual Sewage Disposal Systems and Liquid Waste Management Regulations, these trees will need to be removed and send photographic evidence to SNHD for final approval.

The permit for the updated plumbing fixtures can be released but PLACE A HOLD ON THE FINAL INSPECTION.

RECEIVED BY:

ENVIRONMENTAL HEALTH SPECIALIST:


Joanne Sordahl via email

Sarah George




7406.rpt 1.0.1.03.00

Attachment D: Tenant Improvement Review by SNHD Staff (SR0056341) (Page 2 of 4)



Attachment D: Tenant Improvement Review by SNHD Staff (SR0056341) (Page 3 of 4)



Attachment D: Tenant Improvement Review by SNHD Staff (SR0056341) (Page 4 of 4)



Variance Request for 2625 Barbaradale Cir. September 25, 2025 Page 14 of 18


Seepage Beds: Width 2 ft.; Length 0 ft.; Total Depth ft.; Total effective absorption area in bottom of bed Length of each line Seepage Beds: Width 2 ft.; Length 0 ft.; Total Depth ft.; Total effective absorption area in bottom of bed Length of each line Seepage Pits: Absorption Trenches: Total length of title lines ft. Number of lines ft. Depth of filter material beneath tile ft. Distance between lines ft. Depth of filter material beneath tile ft. Distance between lines ft. Seepage Pits: Number of Pits ft. Diameter Seepage Pits: Number of Pits Diameter Lining Material Diameter Lining Material DATE OF APPROVAL: 19		achment l		- PE FURI	I AND NOTE	.+ OF INSPER	CTION				
CLARK COUNTY HEALTH DISTINCT. TO 2625 Barbaraiale CIT		· 36/	< (A	.)	1110	7E 01 1143FE	CHON			7 7	
SEPTE TANK: Number of Compartments Inside Distance from Well SUBSOIL DISPOSAL: Distance from Well Total effective absorption area in bottom of bed Number of little material beneath tile Length of ach file Absorption of little material beneath tile Trench wilth Distance between lines Total length of tile times Total length of tile				_	CLARK COUNT	Y HEALTH DIST	RICT			+	
Comparison Com				Q 5	SHADOW LANE -	LAS VEGAS, NEV	ADA 89106	1	TELEPHONE	363-1271	
GILADRE, Dorald This was control and the cont	07	2625	Rarbanada	1- 04-	4	GIV-10		788			
SEPTE TANK: Number of Compartments Instance from Well Distance from Nearest Lot Line Instance from Nearest Lo				Ite Life	MOTE					Viunow	
SEPTIC TANK: Number of Compartments Inside Distance from Well Total effective absorption area in bottom of bed Number of Lines Distance between lines Type of filter material Gravel Type of filter material beneath tile Absorption Trenches: Total length of tile lines Depth of litter material beneath tile Total effective absorption area of side wall Total effective absorption area of side wall Total effective absorption area of side wall Distance popp Absorption area of side wall Total effective absorption area of side wall Distance popp Total effective absorption area of side wall Total effective absorption area of side wall Distance popp Total effective absorption area of side wall Total effective absorption area of side wall Distance popp Total effective absorption area of side wall Distance popp Total effective absorption area of side wall Total effective absorption area of side wall DATE OF APPROVAL: 19	1										
SEPTIC TANK: Notified of the following REQUESTED FINAL INSPECTION OF ISDS 1500 Gal 1645 Sq. Pt. Sq. SEL NW- NW S11 T21 inside Difference Compartments It. Distance from Well Distance from Well Distance from Well Distance from Well Capacity It. Distance from Foundation It. Distance from Foundation It. Distance from Foundation It. Total effective absorption area in bottom of bed Number of Lines Distance between lines It. Total length of title lines Depth of filter material beneath tile It. Distance between lines It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Over tile It. Over tile It. Distance between lines It. Distance be									ACTIO	SPECAL	DATE
SEPTE TANK: NOTIFIED OF THE FOLLOWING REQUESTED FINAL INSPECTION OF ISBS 1500 Gal 1645 Sq Pt. St SEL NW NW SII T21 in the second state of the se		-	im(v	OUS ACTION			CLAIRING MICE	OFF.	5	4-	86
REQUESTED FINAL INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1500 Ga1 1645 Sq Pt St SEE NW NW S11 T21 INSPECTION OF ISDS 1600 Ga1 1645 Sq Pt ST			314.04	SACIAL DATI	- WEEK	-	I		- 46	LATRONG - A	CTUAL
REQUESTED FINAL INSPECTION OF ISDS 1500 Gal 1645 Sq Pt 33 SEP NW NW S11 T21 T21 T21 T21 T21 T21 T21 T21 T21 T	CURRENT 1	7 2	ماري الد	STATUS S		THE CUT	751	<u> </u>	ACTED	1	M.FE
SEPTIC TANK: Number of Compartments It; Width Substance from Well Distance from Well Substance from Well Substance from Foundation It; Length	1	Π	112180				12	lo Aci	1 Z	7//2	186
SEPTIC TANK: Number of Compartments Inside Dimension: Length Inside Dimension: Insid				<u> </u>	OTIFIED OF TH	E FOLLOWING	T				
SEPTIC TANK: Number of Compartments Inside Dimension: Length Inside Dimension: Insid	REQ	UESTED FIN	AL INSPEC	TION OF IS	ns 1500	Gal 16/5 S	a R+ S	1 971 1	unua unur	1 077	-
SEPTIC TANK: Number of Compartments Inside Dimension: Length 1s ft.; Width ft.; Liquid Depth 4.D. Subsoil Disposal: Distance from Well Distance from Nearest Lot Line 10 ft. at Front Side Rear 10 Seepage Beds: Width 1 ft.; Length 1 ft.; Distance from Foundation 1st. Total effective absorption area in bottom of bed Number of Lines 1st. Distance between lines 1st. Distance between lines 1st. Distance between lines 1st. Type of filter material beneath tile 1st. Absorption Trenches: Total length of tile lines 1st. Total length of tile lines 1st. Length 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Distance between lines 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Total length of tile lines 1st. Distance between lines 1st. Total effective absorption area of side wall Total effective absorption area of side wall DATE OF APPROVAL: 19						104/ 0	4	1 JUE	SWE AM	5311	121.1
SEPTIC TAMK: Number of Compartments Inside Dimension: Length 19 ft.; Width 5 ft.; Liquid Depth 4 ft. Subsoul Disposal: Distance from Well Distance from Nearest Lot Line 10 ft. at Front Side Rear 10 Total effective absorption area in bottom of bed Number of Lines Distance between lines Distance between lines Distance between lines Type of filter material: Gravel Broken Stones Depth of filter material beneath tile Total length of tile lines Depth of filter material beneath tile Total length of tile lines Depth of filter material beneath tile Total length of tile lines Trench width Total effective absorption area of side walt DATE OF APPROVAL: 19		_ , 	0								
SEPTIC TAMK: Number of Compartments Inside Dimension: Length to ft.; Width ft.; Uquid Depth 4.D. SUBSOIL DISPOSAL: Distance from Well Distance from Nearest Lot Line Inside Capacity It.; Distance from Foundation It.; Distance from Foundation It.; Total effective absorption area in bottom of bed Number of Lines Distance between lines It.; Length It.; Length It.; Length It.; Total length of tile lines It.; Distance between lines It.; Over tile		T	aast	unod 0	1/ to					1	
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Liquid			4.4	4	14					-	
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width Inside Distance from Well Inside Distance from Nearest Lot Line Inside Distance from Foundation Inside Distance from Nearest Lot Line Inside Distance from Foundation Inside Distance from Well Inside Distance from Foundation Inside Distan		1	1								
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width ft.; Width ft.; Width ft.; Liquid Depth Is gal. Distance from Well Distance from Well It. Distance from Foundation Ft. Total From Is gal. Seepage Beds: Width Total effective absorption area in bottom of bed Number of Lines Distance between lines Type of filter material: Gravel Depth of filter material beneath tile Total length of each line It. Total length of tile lines Ft. Total length of tile lines Total length of tile lines Total length of tile lines It. Distance between lines Ft. Number of lines Length of each line ft. Over tile ft. Number of lines Length of each line ft. Total length of tile lines Ft. Number of lines Length of each line ft. Over tile ft. Distance between lines ft. Lining Material DATE OF APPROVAL:		17.00	$Q_A Q V$							-	
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width Inside Distance from Well Is ft.; Width Inside Distance from Well Is ft.; Width Inside Distance from Well Is Distance from Well Is Distance from Well Is Distance from Nearest Lot Line Inside It. Distance from Foundation Is ft.; Under It. Distance from Foundation Is ft. Under It.; Under It.			Jules								
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Liquid					~ //	,					
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Width ft.; Liquid Depth Is ft.; Liquid	M COMED COM				1 11	_					
SEPTIC TANK: Number of Compartments Inside Dimension: Length Is ft.; Width Inside Distance from Well Inside Distance from Nearest Lot Line Inside Distance from Foundation Inside Distance from Nearest Lot Line Inside Distance from Foundation Inside Distance from Well Inside Distance from Foundation Inside Distan		٠ ٧	11		S441444	-0.0			1979	WED BY	
Distance from Well	ВЕРПС	TANK:	st-	2/	X	uzbell			4	7.3-	19 8
Distance from Well	Num Insid	ber of Comp te Dimension	c Length		ft.; Width	S	ft.; Liq	uid Dep			19 8
Seepage Beds: Width	- Num Insid Total	ber of Comp le Dimension Liquid Cap	city		ft.; Width	S	ft.; Liq	uid Dep			19 €
Seepage Beds: Width	Num Insid Total	nber of Comp te Dimension I Liquid Capa NL DISPOSA	city		ft.; Width	S	ft.; Liq	uid Dep			19 8
Width	Num Insid Total SUBSO Dista	ber of Comp le Dimension I Liquid Cap ML DISPOSA ance from W	c: Length	1506	ft.; Width gal.	Distance from Fo	ft.; Liq om Well				19 £
Width	Num Insid Total SUBSO Dista	ber of Comp le Dimension I Liquid Cap ML DISPOSA ance from W	c: Length	1506	ft.; Width gal.	Distance from Fo	ft.; Liq	. 15	th 4 0		19 €
Number of Lines	Num Insid Total SUBSO Dista	aber of Comp de Dimension of Liquid Cap ML DISPOSA ance from We ance from Ne	acity L: ell earest Lot Li	1506	ft.; Width gal.	Distance from Fo	ft.; Liq	. 15	th 4 0		19 £
Distance between lines	Num Insid Total SUBSO Dista	ber of Comple Dimension I Liquid Capa ML DISPOSA ance from Wance from Ne ance from Ne ange Beds: Width	acity	1506 ine10	ft.; Width gal. ft. Dift. at Front	Distance from Fo	ft.; Liq om Well undation Side	. 15	th 4 0		
Type of filter material: Gravel	Num Insid Total SUBSO Dista	ber of Comple Dimension I Liquid Capa ML DISPOSA ance from Wance from Ne ance from Ne ange Beds: Width	Length acity Lit eali earest Lot Lit 2 tive absorpt	1506 ine10	ft.; Width gal. ft. Dift. at Front	Distance from Fo	ft.; Liq m Well undation_ Side Total Dep	. 15	th 4 0		
Absorption Trenches: Total length of tile lines	Num Insid Total SUBSO Dista	ber of Comple Dimension I Liquid Capa NL DISPOSA ance from Wance from Ne ance from Ne ance Beds: Width Total effec Number of	Length acity all carest Lot Li tive absorpt	ine 10	ft.; Width gal.	Distance from Fo	ft; Liq om Well undation Side ; Total Dep	15 pth	th 4 <u>o</u>		f
Absorption Trenches: Total length of tile lines	Num Insid Total SUBSO Dista	ber of Comple Dimension I Liquid Capa DIL DISPOSA DICE From Wance from Ne DISPOSA DICE BERGS: Width Total effect Number of Distance b	Length acity all carest Lot Li carest Lot Li tive absorpt Lines etween line	ine 10	ft.; Width gal. ft. Dift. at Front engthfc ottom of bedft.	Distance from Fo	ft; Liq om Well undation Side ; Total Dep	15 pth	, Rear		sq. ft
Total length of tile lines	Num Insid Total SUBSO Dista	te Dimension I Liquid Capa ILiquid Capa Iliq	Length acity all acity all barest Lot Li live absorpt etween line er material:	ine 10	ft.; Width gal.	Distance from Fo	m Well undation Side Total Dep	# 15 	, Rear		ft .sq. ft ft
Length of each line	Num Insid Total SUBSO Dista Dista Seep	de Dimension I Liquid Capa ILiquid Capa Iliq	acity acity all arest Lot Li tive absorpt Lines etween line er material: iter material	ine 10	ft.; Width gal.	Distance from Fo	m Well undation Side Total Dep	# 15 	, Rear		sq. ft
Depth of filter material beneath tile	Num Insid Total SUBSO Dista Dista Seep	de Dimension Liquid Capa Liqui	acity	ine ft.; Le tion area in b Gravel beneath tile	ft.; Width gal. ft. Dift. at Front engthft. ft., B	Distance from Fo	m Well undation Side Total Department of tile line Over tile	oth	, Rear		ft
Depth of filter material beneath tile	Num Insid Total SUBSO Dista Dista Seep	te Dimension Liquid Cape Liqui	tive absorpt Lines 4 etween line er material: there is hof tile line	ine ft.; Le tion area in b Gravel beneath tile	ft.; Width gal.	Distance from Fo	m Well undation Side Total Department of tile line er of lines	oth	Rear .		ft . sq. ft ft ft
Seepage Pits: Number of Pits Effective Depth Total effective absorption area of side wall DATE OF APPROVAL: 19 Diameter Lining Material	Num Insid Total SUBSO Dista Dista Seep	de Dimension I Liquid Capa II Liquid	tive absorpt Lines der material: the material: the file line at the line at th	ine 10	ft.; Width gal.	Distance from Fo	ft; Liquin Well	oth	, Rear:		ft ft ft
Number of Pits	Num Insid Total SUBSO Dista Dista Seep	de Dimension I Liquid Capa II Liquid	tive absorpt Lines der material: the material: the file line at the line at th	ine 10	ft.; Width gal.	Distance from Fo	ft; Liquin Well	oth	, Rear:		ft ft ft
Total effective absorption area of side wall DATE OF APPROVAL: 19 11 12 13 14 15 16 16 16 16 16 17 18 18 18 18 18 18 18 18 18	Num Insid Total SUBSO Dista Dista Seep	iber of Comple Dimension I Liquid Capa III. DISPOSA INC.	tive absorpt Lines der material: the material: the file line at the line at th	ine 10	ft.; Width gal.	Distance from Fo	ft; Liquin Well	oth	, Rear:		ft ft ft
DATE OF APPROVAL: 1986	Num Insid Total SUBSO Dista Dista Seep	ber of Comple Dimension I Liquid Capa Disposal Liquid Liquid Liquid Capa Disposal Dispo	tive absorpt Lines er material: the material	It; Le ion area in b Gravel _ beneath tile ft. beneath tile	ft.; Width gal. ft. Di ft. at Front ength 7c ottom of bed ft. ft. Total effective	Distance from Fo	m Well undation Side Total Deplet Of line th of tile lin Over tile er of lines ween lines a on sides Over tile	oth	, Rear:		ft ft ft
DATE OF APPROVAL: 19 86 MULTINE	Num Insid Total SUBSO Dista Dista Seep	de Dimension I Liquid Capa ILiquid Iliqui	tive absorpt Lines er material: the material	IL; Le ion area in b Gravel _ beneath tile ft.	ft.; Width gal.	Distance from Fo	ft; Liquin Well	oth	, Rear:		-
19	Num Insid Total SUBSO Dista Dista Seep	de Dimension I Liquid Capa I Total effect I Liquid Capa I	tive absorpt Lines ther material these ach line the material ther material ther material the mat	ine 10 It; Le ion area in bos Gravel beneath tile ft beneath tile	ft.; Width gal.	Distance from Fo	ft; Liquin Well	oth	, Rear:		sq. ft
Sanitarian	Num Insid Total SUBSO Dista Dista Seep	ber of Comple Dimension I Liquid Cape II Liquid Cape III DISPOSA I	tive absorpt Lines 4 the material: the material the mater	ine 10 It; Le ion area in bos Gravel beneath tile ft beneath tile	ft.; Width gal. ft. Dift. at Front ength	Distance from Fo	ft; Liquin Well	oth	, Rear:		sq. ft

FILE COPY

Attachment E: Final Inspection Report and Plot Plan for ON0010273 (Page 2 of 3)

	THRE DIG.				
	c torter		HEALTH DISTR		TELEPHONE 383 1271
DIST LOCATION			City . TOW		
07 2625 BA	RBARADALE CIRCLE			LAS VEGAS	
CTI HODE D	14	MOTE	_		18 APPROVE
GILMORE, Do	naid		Tass	Hardin	SCHEDULED ACTION
0 081	_				ACTION DATE
	STATUS SPECIAL SATE	. I WOLATH	W WO	ATIONS - ALLEBORD	\$ 2/26/86
T Sav C T ACTION I	1 1	CAN DATE THAN			
ST 10 6 21.	JU.	11:0		12 12	2 3/26/80
	TNO NO.	TIFIED OF THE	FOLLOWING	112/12/	2/26/6
	OF ISDS. CONFIRM				
645 SQ FT LEACH	BED (30 MIN PERC I	RATE). E≒SE	NW NW Sec 1	1 T21S R60E	(BARBARADALE/Redwood
	C 11 T	^^ 4	0	2/: 2	^
Unea (OK for ins	Jallatia	ap Few	el puela	<i>y</i> –
			<u> </u>	U	
() 0.0	removel				
	- Nammer	\ /			
		1	0		
14	4.60	Yeuro	1000		NEVENDO 67
7 1677	T) Montale	املالا الا			3-27- 198
•		part	~		
		V			
EPTIC TANK:	2 .				
Number of Compart	ments 2 Length 10	Type of	Material C	0N/4	·
Inside Dimension:	Length	ft.; Width	5	ft.; Liquid D	epth <u>H, o</u>
rotal ciquid Capacii	ty	gai.	Distance fro	m Well	
UBSOIL DISPOSAL:					
Distance from Well		ft. Di	stance from Fo	undation	f
Distance from Near	est Lot Line	ft. at Front		Side	f
Seepage Beds: Width	ft · Lo	ooth	4	· Total Denth	
Total effective	e absorption area in bo	ttom of bed			sq. f
Number of Lir	nes		Length of eac	ch line	
	ween lines	ft.	Total lengt	h of tile lines	•
Distance bety	material: Gravel				
Type of filter a	amotorial bases at an	, в	roken Stones		Other
Type of filter a	material beneath tile		roken Stones		Otherf
Type of filter Depth of filter Absorption Trenche	r material beneath tile . es:		roken Stones . ft.	Over tile	f
Type of filter Depth of filter Absorption Trenche	r material beneath tile . es:		roken Stones . ft.	Over tile	f
Type of filter Depth of filter Absorption Trenche Total length of Length of eac	r material beneath tile	ft.	ft. Numb	Over tile	
Type of filter Depth of filter Absorption Trenche Total length o Length of eac Trench width	r material beneath tile	ft.	ft. Numb	Over tile	enches f
Type of filter Depth of filter Absorption Trenche Total length o Length of eac Trench width	r material beneath tile	ft.	ft. Numb	Over tile	
Type of filter Depth of filter Absorption Trenche Total length of Length of eac Trench width Depth of filter	r material beneath tile	ft.	ft. Numb	Over tile	enches f
Type of filter Depth of filter Absorption Trenche Total length of eac Trench width Depth of filter Seepage Pits:	r material beneath tile	ft. Total effective	ft. Numb Distance bette absorption are	over tileer of lineseveen linesea on sides of tr	enchesf
Type of filter Depth of filter Absorption Trenche Total length of Length of eac Trench width Depth of filter Seepage Pits: Number of Pit Effective Dep	r material beneath tile	ft. Total effective	ft. Numb Distance bette absorption are ft.	over tile er of lines ween lines a on sides of tr Over tile	enchesf
Type of filter Depth of filter Absorption Trenche Total length of Length of eac Trench width Depth of filter Seepage Pits: Number of Pit Effective Dep	r material beneath tile	ft. Total effective	ft. Numb Distance bette absorption are ft.	over tile er of lines ween lines a on sides of tr Over tile	enchesf
Absorption Trenche Total length of eac Trench width Depth of filter Seepage Pits: Number of Pit Effective Dep Total effective	r material beneath tile. Is: If tile lines	ft. Total effective	ft. Numb Distance bette absorption are ft.	over tile er of lines ween lines a on sides of tr Over tile	enchesf
Absorption Trenche Total length of eac Trench width Depth of filter Seepage Pits: Number of Pit Effective Dep Total effective	r material beneath tile	ft. Total effective	ft. Numb Distance bette absorption are ft.	over tile er of lines ween lines a on sides of tr Over tile	enchesf

Attachment E: Final Inspection Report and Plot Plan for ON0010273 (Page 3 of 3)



Attachment F: Septic Tank Inspection by Master Jetting Sewer Specialist LLC

MASTER J	ETTING
SEVER SPECA NV#20212142881 Off	1360 lce/Cell # 702.592.9980
Name: Sean Connell Tech Name:	Kevin Invoice Date: 6-20-25
Phone: 202-300-4294	Billing to:
Address: 2625 Barbardale Cir	
Las Vegas, NV 89146	Phone:
	Address:
- Septic System	Inspection
Upon arrival remov	
to inspect water les	
normal operating levi	
Indicating that Leach	
Functioning, with no	
compromise would be	present (at this time) We
had LV Septic service	ce tank (empty) in
Order for Visual/Ca Septic System - No c	mera inspection of
Septic System - No c	ompromise could be
Found (at this time) Sys	item appears to be
in great operating o	condition (at this time)
Term & Conditions	Form of Payment
I have been informed that during the process of unclogging/cleaning of my sewer system/line of the possibilities	Cash \$ Check #
That water damage/flood may occur, And that MJSS is not responsible.	Card
Acknowledge/ Accept tull responsibility for any and all damages that may occur.	Name Number
1 Accelerational Processing to the second of	Exp CVV
I have been informed of the possibility of the equipment(I.E-jetter hose, head, etc.) becoming stuck in the sewer line and	Billing Zip
of the equipment(i.e.) enter nose, need, etc.) becoming stock in the sewer line and that I Acknowledge/ Accept the responsibility of the replacement cost in the event of this happening.	
I understand and agree to all the Terms & Conditions of this service contract.	I agree to MJSS charging my credit card for the total contracted price plus any card fees that may apply
	Thank you for your business!

Attachment G: Public Notice



PUBLIC NOTICE

The Southern Nevada District Board of Health will conduct a PUBLIC HEARING on Thursday, September 25, 2025 at 9:00 AM during its regular monthly meeting in the Red Rock Conference Room at the Southern Nevada Health District at 280 S. Decatur Blvd., Las Vegas, Nevada, to approve or deny a variance request filed by Sean Connell ("Petitioner"), to allow existing trees to remain within 10 feet of the existing septic system (SNHD Permit # ON0010273) on the property located at 2625 Barbaradale Cir., Las Vegas, NV 89146, APN 163-11-111-004.

The variance is requested to allow the Petitioner to obtain approval for a Tenant Improvement in accordance with Section 3 of the *Southern Nevada District Board of Health Regulations Governing Individual Sewage Disposal Systems and Liquid Waste Management* and to allow future building permits to be issued. The variance will allow the existing trees to remain over the leach field.

All interested persons may appear at the hearing and state their positions. All written and oral submissions will be considered by the Southern Nevada District Board of Health. Written comments must be forwarded by September 24, 2025 to:

Daniel Isler, P.E., REHS Environmental Health Engineer/Supervisor Southern Nevada Health District P.O. Box 3902 Las Vegas, Nevada 89127 isler@snhd.org

The variance application is available for review at the Southern Nevada Health District, 280 S Decatur Blvd, Las Vegas, Nevada 89107. Please contact Daniel Isler at (702) 759-0660 to schedule an appointment to review the application during the normal business hours of 8:00 AM to 4:30 PM.

- S -	September 9, 2025
Karla Shoup, REHS	Date
Acting Director of Environmental Health	